



WORK HOLDING FIXTURE SMART GRIP


3-axis machining center 6-FACE MACHINING



6-FACE MACHINING



- A** Dovetail grooving
- B** 1 to 4-face machining
- C** 5th face machining
- D** 6th face machining



Centering Aligning




Deburring Cutting chips cleanup



PROCESS INTEGRATION


6-face machining with one cycle




One chucking allows superior accuracy machining



Off-line set-up




In-line measurement




System



Rigidity




Accuracy




Machining example



For Automation



In-line measurement



Off-line measurement

